Baanto - Dashboard: Calibration in Windows

Applies to: Baanto (Shadow Sense) Touch Frames
Symptom(s): Misaligned Calibration
Affected OS: Windows 10
Prerequisite Software: <u>Dashboard</u>

1. To download **Dashboard** click on the link above.

2. To begin the installation, Click **Next** on the **ShadowSense Dashboard** installation file.

3. Select all files that are not already installed and Click **Install**.

4. Make sure your touch frame is connected to both USB and Power and open Dashboard. Your touch device will automatically be detected by the software. Click on **configuration**.

5. In the left-hand pane, scroll down and click on **Transformations**, then click the **reset** button. After the calibration has been reset, click on the **calibrate** button.

6. Click **OK** when prompted.

7. Starting outside of the circles, drag your finger to the center of the crosshairs when prompted. To cancel and restart, click on or tap abort.

Align touch with markers and hold until complete

Time remaining
58

| back | | abort |

8. After calibration, be sure to click on **Apply** to save the changes.

reset   load   apply

9. Test the new calibration in your content or in a separate program like Microsoft Paint to confirm calibration was successful.

10. If the above steps do not resolve the issue, please contact the TSI Touch Customer Service team at 802-874-0123 Option 2; email: support@tsitouch.com; or by visiting our TSI Touch website and clicking on the red "Help" icon in the lower right corner of the webpage.